

Zohal Office - Bangalore North

Karnataka State Pollution Control Board

1st Floor, Urban Eco Park,
100 Feet Road, 3rd Phase,
Peenya Industrial Area, Bengaluru-560 058.
Telefax: 080-28396559
Mobile : 9845320200

ವಲಯ ಕಛೇರಿ : ಬೆಂಗಳೂರು ಉತ್ತರ

ಕರ್ನಾಟಕ ರಾಜ್ಯ ಮಾಲಿನ್ಯ ನಿಯಂತ್ರಣ ಮಂಡಳಿ

1ನೇ ಮಹಡಿ, ಅರ್ಬನ್ ಇಕೋ-ಪಾರ್ಕ್,
100 ಅಡಿ ರಸ್ತೆ, 3ನೇ ಹಂತ, ಪೀನ್ಯಾ ಕೈಗಾರಿಕಾ ಪ್ರದೇಶ,
ಬೆಂಗಳೂರು-560 058.
ದೂರವಾಣಿ : 080-28396559
Email: seon@kspcb.gov.in



towards a cleaner Karnataka

NO; KSPCB/RSEO/BNG-N/2019-20/

DATED:

**Inspection Report of Sri. D.R. Kumaraswamy, Senior Environmental Officer,
Bangalore North**

Attention:

Name of the industry	M/s. Sushanth Environmental Technologies (Common Biomedical waste Treatment Facility), SY No. 24/2, Amaravathi Village, Harihar-Tq, Davanagere Dist
Date of inspection	15.05.2019
Staff accompanied	Sri Lingaraju Sample collator
Industry staff present	Sri Jayadeva, Manager

a) Discharge of effluents under the Water Act :

Sl. No.	Water Code	WC(KLD)	WWG(KLD)	Remark
1	Domestic Purpose	0.5	0.4	Septic tank and soak pit
2	Manufacturing Processes	2.0	1.8	Treated recycled back to scrubber

b) Discharge of Air emission under the Air Act from the following stacks etc.

Sl.No	Types	Applied Qty/Month	Unit
1	Common Biomedical Incinerator	30	Ton

Content Conditions

A)	Treatment and Disposal of Effluents under the Water Act.
I	NA
2(a)	Complied
2(b)	NA
3(a)	Scrubber effluent treated and recycled back
3(b)	NA
4	Not complied
5	Noted by Factory authority
6	Complied
7	Complied
8	Complied
B)	<u>Emission</u>
1	Complied (Not monitored)
2	Complied
3	Noted by Factory authority
c)	<u>Water cess</u>
1.	NA
D)	<u>Monitoring & reporting</u>
1	Not complied
2	Complied
E)	<u>Solid waste</u>
1	Complied
2	Complied
F)	<u>Noise pollution control</u>
1	Complied
G)	<u>Hazardous Waste</u>
1	Complied
H)	<u>General Conditions</u>
1	Complied
2	Noted by FA
3	Not complied

4	Noted by FA
5	Noted by FA
6	Complied
7	Complied
8	Complied
9	Noted by FA
10	Noted by FA
11	Not Complied more trees has to be planted
12	Not Complied
13	Noted by FA
14	Not Complied
15	Complied

The BMW incinerator was inspected as per Board office memo Random inspection vide No. PCB/05/EGV-16/893 dated:03.05.2019

The industry is having valid consent (20.02.2018 to 30.06.2020) and authorization under BMW Rules, 2016 (01.07.2015 to 30.06.2020). The incinerator was under operation. The OCEMS was not working. The scrubbed effluent is settled in series of tanks and recycled back to scrubber. The Roof of the building was damages (AC Roof). There was black smoke emitted from the chimney, when they feed more waste to incineration. They were advised to adjust the feed rate, so that there shall not be any visible emission. They operate only 2 to 3 hours per day.


Senior Environmental Officer,
Bangalore North