## Format for uploading the CETP monitoring data on SPCBs website

SI. No.	Name and Address of the CETP	Capacity (MLD)	Design Inlet quality	Final effluent quality standards or ZLD condition	Date of monitoring	Waste water treated in CETP (MLD)	Wastewater bypassed untreated in the area. If any (MLD)	Observed Inlet quality	Observe d Final effluent quality	Status of online CEQMS	Status of hazardous waste storage/disposal
1	2	3	4	5	6	7	8	9	10	11	12
1	CET Plant Malur	Easily	Easily	Final	27.12.2016	0.035 to	NIL		Annexure	Installed	ETP Sludge 8.7
	Private Limited	Biodegrad	Biodeg	effluent		0.040			enclosed		Tons disposed on
	Plot No. 64 & 65,	able	radable	quality		Daily					03.10.2016, &
	KIADB Industrial	effluent –	effluen	standards		average					Stored about
	Area, Malur, Kolar	0.06	t –								11.89 Tons &
	District.	High TDS	0.06								Used Oil of about
		effluent –	MLD	- *							350 Ltrs stored in
		0.08	High	3	73						drums as on
			TDS								27.12.2016.
			effluen								
			t –								
			0.08M								
			LD								

ENVIRONMENTAL OFFICER, REGIONAL OFFICE, KOLAR.



# KARNATAKA STATE POLLUTION CONTROL BOARD CENTRAL ENVIRONMENTAL LABORATORY

### AN ISO/IEC 17025:2005 (NABL) ACCREDITED LABORATORY AN ISO 9001:2008 CERTIFIED LABORATORY

Email:centrallab@kspcb.gov.in Website: http://kspcb.gov.in

6.ರಾ ಮಾ.ರಿ.ಮಂ., ನಿಸರ್ಗಭವನ್), ೭ ನೇ 'ಡಿ'ಮುಖ್ಯ ರಸ್ತೆ, ತಿಮ್ಮಯ್ಯ ರಸ್ತೆ,ಶಿವನಗರ್, ಚಂಗಳೂರು - ೫೬೦೦೦

K.S.P.C.B., "Nisarga Bhavan" 7<sup>th</sup> D Cross, Thimmaiah Road, Shivanagar, Bangalore – 560079

#### ANALYSIS REPORT

Date: 13-01-2017

M/s. CET Plant Malur Private Limited,	Page 1 of 1
Malur Industrial Area, Malur Taluk, Kolar District.	DATE OF COMMENCEMENT OF TEST:24-12-2016
Kolar	DATE OF COMPLETION OF TEST:
22-12-2016	06-01-2017
24-12-2016	SAMPLE REPORT NO: R-II-2309
Sample collected from ETP	SAMPLE NO : R-II-2309
	Malur Industrial Area, Malur Taluk, Kolar District.  Kolar 22-12-2016 24-12-2016

SI No.	Parameters	Unit	Standard	Result	Range of testing/Limit of Detection	Test Method
1,	pH @ 25°C	pH Unit	6.0-9.0	8	1 to 14	IS:3025 (Part 11):1983
2.	Total Suspended solids	mg/L	100	6	1 to 500 mg/L	IS:3025 (Part 17)-1984
3.	Ammoniacal Nitrogen as N*	mg/L	50	0.12	:	IS:3025 (Part 34):1988
4.	Total Dissolved Solids	mg/L	2100	434	10 to 5000 mg/L	IS:3025 (Part 14)-2013
5.	Chloride as Cl	mg/L	600	65	1 to 5000 mg/ L	IS:3025 (Part 32)-1988
6.	Sulphate as SO <sub>4</sub>	mg/L	1000	22	l to1000 mg/L	IS:3025 (Part 24):1986
7.	Hexavalent chromium as Cr <sup>+6</sup>	mg/L	0.1	BDL	0.05 to 100 mg/L	APHA 22 <sup>nd</sup> edition 3500- Cr B : 2012
8.	Oil & grease	mg/L	10	BDL	L to 100 mg/L	APHA 22 <sup>nd</sup> edition. 2012;5520B;
9.	Cyanide*as CN	mg/L	0.2	BDL		IS:3025 (Part 27)1986
10.	Copper *	mg/L	3.0	0.03	0.5 to 100 mg/L	IS:3025 (Part 42):1992
11.	Lead	mg/L	0.1	BDL	0.2 to 100 mg/L	IS:3025 (Part 47):1994
12.	Zinc	mg/L	5.0	0.14	0.1 to 100 mg/L	IS:3025 (Part 49):1994
13.	Nickel	mg/L	3.0	BDL	0.1 to 100 mg/L	IS:3025 (Part 54):2003
14.	Total Chromium *	mg/L	2.0	0.1	0.2 to 100 mg/L	IS:3025 (Part 52):2003
15.	Cadmium	mg/L	2.0	BDL	0.1 to 100 mg/L	IS 3025 (Part 41):1992

Note: 1. The above results pertain only to the sample tested.

2. The report shall not be reproduced without the written approval of the laboratory.

3. \*- Tests are not under the scope of NABL Accreditation.

4. BDL: Below Detection Level.

5. Samples will be stored for a period of 15 days from the date of issue of report.

Authorized Signatory Chemical)
H.M.Shivakumar
Scientific Officer

Scientific Offi

Formate for uploading the CETP monitoring data on SPCBs website

SI. No.	Name and Address the CETP		Design Inlet	Final Effluent quality	Date of monitoring	Wastewater treated inCETP (MLD)`	Waste water bypassed unt: eated in the area, if any (MLD)		Effluent quality	Status online CEQMS	Status of hazardous waste storage/ disposal
1	2	3	4	5	6	7	8	9	10	11	12
1	M/s. Govind Solvents (P) Ltd, Plot No. 19 (P) 22, KIADB Industrial Area, Ancheplaya, Künigal	50 KLD of biodigredable effluent , 25 KLD of High TDS	50 KLD of biodigredable effluent , 25 KLD of High TDS	pH-5.5 to 9.0 BOD- 100 COD-600 DS-2100, TSS- 200,	21.12.2016,	50 KLD of biodigredabl e effluent , 25 KLD of High TDS	No bypasses or untreated effluent discharged out of industry premisess is noticed during the inspection.	monitored	DS-1702, TSS-28, AR enclsoed as	continous Online monitoring equipment installed but not connected to CPCB and SPCB survers.	Stored in closed room.

Ly

# Format for uploading the CETP monitoring data on SPCBs website: Region office Doddaballapura

Sl. No	Name and Address the CETP	Cap acity (ML D)	Design Inlet quality	Final effluent quality standards or ZLD condition	Date of monitorin g	Wastewat er treated in CETP (MLD)	Wastewat er bypassed untreated in the area, if any (MLD)	Observ ed Inlet quality	Observed Final effluent quality	Status of online CEQMS	Status of hazardous waste Storage/disposal
1	2	3	4	5	6 14.7.2016	7 0.07MLD	8 Nil	9 Not	10 Furnished	11 Installed	Provided closed shed for
1	M/s. Eco Green Solutions Systems	0.1 MLD	de	ished the tails in exure - I	14.7.2010	0.07 [112]		done	the details in annexure - I	online monitoring system	storage of Hazardous waste. generated from the CETP. They are disposing same to TSDF,
	Pvt. Ltd.,	5	P	ished the	23.3.2016	1 MLD	Nil		ned the details	Not Installed	Provided closed the
2	2 KIADB, Apparel Park		de	Furnished the details in annexure - II		(M/s Scotts Garments effluent)		in a	nnexure - II	online monitoring system	shed for the storage of ETP sludge and deposing to TSDF.

Environmental officer Regional Office, Doddaballapura.

W W

## Annexure -I day

Name of Industry:

M/s. Eco Green Solutions Systems Pvt. Ltd.,

Address:

No.48/A-4, KIADB Indl. Area,

Doddaballapura, Bangalore Rural Dist.

Sl. No	Parameter	Unit	Design Inlet quality	Final effluent quality standards	Observed Final effluent quality date of monitoring 14.07.2016
		U.U.nit	5.5	5.5-9.0	7.3
1	pH	pH Unit	3.3	2100	694
2	Total Dissolved Solids	mg/L		200	4.0
3	Total Suspended Solids	mg/L		600	194
4	Chloride	mg/L	-	000	
5	Biochemical Oxygen Demand	mg/L		100	3.0 79.0
	(3 days @ 27 0C)	mg/L		1000	79.0
6	Sulphate	mg/L	20	10	
7	Oil & grease	-		60	34.99
8	Percent Sodium*	%		0.2	BDL
9	Cyanide*	mg/L	2.0		0.31
10	Boron	mg/L	2.0	0.2	Nil
11	Oil & Grease	Mg/L	20	10	1411

## Annexure -II

Name of Industry:
Address:

CETP Owned by KIADB

Apparel Park, Doddaballapura,

Bangalore Rural Dist.

Sl. No	Parameter	Unit	Design Inlet quality	Final effluent quality standards	Observed inlet quality	Observed final effluent Quality(RO Permeate)Date of monitoring 23.03.216
		pH Unit	7.0	5.5 to 9.0	6.4	6.8
1	рН		16.0	200	78.0	4.0
2	Total Suspended Solids	mg/L	1668.0	2100	1790	700
3	Total Dissolved Solids	mg/L	224.0	250	544.0	19.0
4	Chemical Oxygen Demand	mg/L		30	310.0	3.0
5	Biochemical Oxygen Demand	mg/L	62.0	30		
	(3 days @ 27 0C)	1 //	21.3	100	58.5	4.47
6	Nitrate	mg/L	368	1000	368.0	124.8
7	Sulphate	mg/L		0.1	0.05	•
8	Lead	mg/L	BDL	3	0.02	•
9	Copper	mg/L	BDL	5	0.2	
10	Zinc	mg/L	0.1	3	0.04	7.
11	Nickel	mg/L	0.04	10	0.05	
12	Total Chromium	mg/L	0.03			

Environmental Officer

Karnataka State Pollution Control Board

Doddaball

ar

S	Name and	Capa	Design Inlet	Final effluent	Date of	Waste	Waste water	Observed	Observed	Status of	Status of
1.	Address of the	city	quality	quality	monitoring	water	bypassed	inlet	final	online	hazardousw
N	CETP	(ML	(mg/l)	standards in		treated in	untreated in	quality	effluent	CEQMS	aste
0		D)		mg/L or ZLD		CETP	the area, if		quality		storage/dis
				conditions	1 to 1	(MLD)	any (MLD)				posal
1	2	3 *	4	5	6	7	8	9	10	11	12
1	M/s Fishmeal and Oil Manufacturers Association (Regd.) Port No. PIWT-1/L&D-1/2008 Sea Road, Kotepura, Ullala, Mangaluru	0.6	pH- 5.5-9 SS -400 Oil & grease - 30 COD - 25000 BOD - 15000	pH- 5.5 -9 SS- 100 BOD - 30 COD- 250 Oil & Grease - 10 Sulphides- 2 Lead- 0.1 (Treated effluent is finally discharged into sea)	09.12.2016 21.11.2016 24.10.2016	0.6	Nil		Analysis reports enclosed	Not provided	NA

Note: Personal hearing held on 31.12.2016 at Board office and assured to provide CEQMS within 2 months time.

Yours faithfully,

ENVIRONMENTAL OFFICER KSPCB, MANGALURU

#### Format for uploading the CETP monitoring data RO- SARJAPURA

SI. No.	Name and Aredss the	Capacity	Design Inlet	Final effluent quality sta	andards or ZLD conditions	Date of	Waste water treated in	Waste water by pasees untreade in	Observed	Observed final effluet	Status of	status of hazarous waste
31. NO.	CETP	( KLD)	quality	Characteristics	Tolerance limits	manitoring	CETP	the area, if any (MLD)	inlet quality	quality	online CEQMS	staroge/ disposal
1	2	3	4	5		6	7	8	9	10	11	12
				рН	6.0-9.0							
				Temperature	Shall not exceed 5 C above the ambient temperature of the receiving body						Slu in	1). HW (ETP
	M/S. VIWA			Oil & Grease, mg/lt	10							Sludge) Stored in designated
	ECO CLUB (CETP),			Suspended Solids, mg/lt					storage area 2). Disposed			
	Opp. Shed No B-5 & 6,			Ammonical Nitrogen, (as Cl), mg/lt	50	15.12.2017	16 to 18 KLD		Observed	Clear		to land fill M/s. Mother
1	Veerasandra Industrial	20 KLD	16 KLD	Total Residual chloride (as Cl), mg/lt	1						Online monitoring	Earth Enviro Tech Pvt Ltd,
1	Estate, Hosur Road,	20 KLD	10 KLD	Cadmium (as Cd), mg/lt	(Mon	(Monthly)					system provided	Located Kanakapura
	Anekal			Nickel (as Ni), mg/lt	3							Road,
	Taluk,			Zinc (as Zn), mg/lt	5							Harohally.
	Bengaluru - 560 100.			Hexavalent Chromium, mg/lt	0.1							3). Accumulated
	300 100.			Total Chromium as (Cr), mg/It	2							Qty as on 23.01.2017 is
				Copper (as Cu), mg/lt	3							about 1.5 MT.
				Lead (as Pb), mg/lt	0.1							
				Iron (as Fe) mg/lt	3							
				Total Metal, mg/lt	10							

(Column 1-5: Basic Information on CETP; Column 6-12: Inspection -s[ecific information on observed performance during the inspection)

Note: Intel & Final effluent quality to be reported in terms of pH, BOD, COD, TSS, TDS and relevant special parameter

Environmental Officer, Regional Office - Sarjapura.

				Format for up	loading t	he CETP m	onitoring data	on SPCBs Websit	e		
Sl No.	the CETP	(MLD)	quality	condition	Date of monitoring	CETP(MLD)	Waste water bypassed untreated in the area, if any(MLD)	Observed inlet quality	Observed final effluent quality	Status of online CEQMS	Status of Hazardous waste storage/disposal
1	2	3	4	5	6	7	8	9	10	11	12
1	M/s Pai & Pai Chemicals (I) Pvt Ltd., Plot No.29 A, KIADB Indl Area, Kumbalgodu, Bangalore-74	0.3	-	pH-6.6-7.6 BOD-Not mentioned COD-Not mentioned TSS-71-76 mg/l TDS-1612-1750 mg/l	28.09.2016	0.1	Not bypassed	Only heavy metals parameters have been analysed.	pH- 7.7 BOD-Not analysed COD-Not analysed TSS- 10.0 mg/l TDS-514 mg/l	CEQMS was in	Generated quantity- Used Oil-0.5 KL/A, ETP Sludge-480 MT/A. Accumulated-Used oil- 98.5 ltrs CETP Sludge- 47,951 kgs , Disposed- Used oil- Nill Sludge-89,660 kgs
2	M/s Pai & Pai Chemicals (I) Pvt Ltd.,No.25D, #25/D, 1st Phase, Kumbalgodu Industrial Area, Bangalore-560074		pH- BOD- 500- 50,000 mg/ltr COD- 1500- 1,50,000 mg/ltr TSS- TDS-	pH-6.6-7.73 BOD-34-66 mg/l COD- Not mentioned TSS- 70-83 mg/l TDS-1600-1732 mg/l	28.09.2016	0.04	Not bypassed	Raw effluent sample collected from one of the industry while dischargiing to Equilization tank, pH-4.9, BOD-18600 mg/l, COD-31776 mg/l, TSS-2560mg/ltr, TDS-11720 mg/l	pH- 7.5 BOD-14 mg/l COD-Not analysed TSS-6.0 TDS-1128 mg/l	but not connected to server	Generation-Used oil-0.1 KL/A, Oil & Grease skimming residue-0.3 MT/A. Accumulated-Used oil- 11 ltrs Skimmed residue- 2.5 ltrs Disposed, Used Oil- 5.5 ltrs Skimmed residue-1.5 ltrs

Name and address of the CETP	Capacity (MLD)	Design Inlet quality (mg/l)	Final effluent quality standards of ZLD condition Date of	Waste water treated in CETP (MLD)	Wastewater bypassed untreated in the area, if any (MLD)	Observed Inlet quality		Observe	d Final effluent	quality			Status of online CEQMS	Status of hazardous waste storage/disposal
							Parameters pH@25°C	Standard and unit mg/l 5.5-9.0	06.04.2016 8.0	30.06.2016 6.8	18.07.2016 7.1	24.10.2016 7.5	-	
							Total Dissolved Solids	2100	1384	2266	1888.0	1438		
							Total Suspended Solids	600	8.0**	54.0	50.0	10.0		
							BOD (3 days@27°C)	350	22	218	105.0	16.0		
							Copper	3.0	BDL**	0.2	BDL	BDL		
		Designed for					Zinc	1.5	0.2**	0.6	0.2	BDL		
		treating tannery	Final effluent				Nickel	3.0	BDL**	BDL	BDL	BDL	Installed. At	
Lidkar Tannery Enviro			quality to meet				Total Chromium	2.0	BDL**	0.08	BDL	BDL	present not	MOU made with TSDF
Control Systems Ltd.,	1	pH-8,	BWSSB sewer	0.2	Not by	Sample will	Iron	3.0	0.2**	5.6	3.7	0.3	working as short circuit which has	of Ramky. 10 tonnes
Tannery Road, K.G.Halli, Bangalore-560045		BOD-1600 COD-3400	discharge		passed	be collected	Cadmium	1.0	BDL**	BDL	BDL	BDL	burnt the PCB of	stored as on 24.10.2016.
Ballgalore-300043		SS-2250	standards				Lead	1.0	BDL**	BDL	BDL	BDL	display unit.	24.10.2010.
		DS-16,250					Sulphate	1000	148	339	409.0	153		
							Fluoride	1.5	0.290**	0.29	0.21	0.37		
							Hexavalent chromium	2.0	BDL**	BDL	BDL	BDL		
							Cyanide*	0.2	BDL	BDL	BDL	BDL		
							Oil & grease	20	Nil	Nil	Nil	Nil		
							Phenolic compound	5.0	BDL**	BDL	BDL	BDL		
							Ammonical Nitrogen*	50	24.5	5.3	6.7	4.9		
									Conforms	Non conforms	Non conforms	Conforms		