

Classification of Water Quality under National Water Quality Monitoring Programme from April - 2020 to December-2020

River Water Quality – Global Environmental Monitoring System (GEMS)

Sl. No	Stn code	Monitoring Location	River	Regional Office	Apr-20		May-20		Jun-20		Jul-20		Aug-20		Sep-20		Oct-20		Nov-20		Dec-20		Jan-21		Feb-21		Mar-21	
					Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI
1	29	At Ullanur Bridge	Tungabhadra	Raichur	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
2	33	At Balamuri Kshetra	Cauvery	Mysuru	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
3	34	At Satyagala Bridge	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
4	38	At Honnali Bridge	Tungabhadra	Davangere	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
5	41	At Cause way Suttur	Kabini	Mysuru	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						

River Water Quality – Monitoring of Indian National Aquatic Resource System (MINARS)

Sl. No	Stn code	Monitoring Station	River	Regional Office	Apr-20		May-20		Jun-20		Jul-20		Aug-20		Sep-20		Oct-20		Nov-20		Dec-20		Jan-21		Feb-21		Mar-21	
					Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI
1	1028	At Tintini Bridge	Krishna	Raichur	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
2	1029	At Haralahalli Bridge	Tungabhadra	Davangere	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
3	1091	D/S of KIOCL, Malleshwar	Bhadra	Hassan	B	S	B	S	B	S	B	S	B	S	B	S	B	S	B	S	B	S						
4	1163	W.A. Point to Gokak Town	Ghataprabha	Belgavi	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
5	1164	W.A. Point to Hubli-	Malaprabha		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
6	1165	At D/S of Kanakapura	Arkavathi	Ramanaga	D	US	D	US	D	US	D	US	D	US	E	US	D	US	E	US	D	US						
7	1166	At D/S of Bridge Halagur	Shimsha	Mysuru	*		*		*		*		*		C	S	C	S	C	S	C	S						
8	1167	At D/S of Bridge near	Bhima	Raichur	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
9	1168	At D/S of Shimoga	Tunga	Davangere	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
10	1169	Near Holehonnur	Bhadra	Davangere	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
11	1170	At D/S of Devasagar Bridge	Krishna	Raichur	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
12	1171	At D/S of Road Bridge at Shrirangapatna	Cauvery	Mysuru	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
13	1181	At D/S of Narayana pura	Krishna	Belgavi	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
14	1182	At D/S of Ugarkhurd	Krishna		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
15	1183	At D/S of Road Bridge Ghanagapur Village	Bhima	Kalaburagi	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
16	1184	At Ferozabad	Bhima		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
17	1185	At D/S of Mudhol Road Cross Bridge	Ghataprabha	Belgavi	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
18	1186	At D/S of Aihole Town	Malaprabha		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
19	1187	At D/S of Khanapur Village	Malaprabha		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						

Classification of Water Quality under National Water Quality Monitoring Programme from April - 2020 to December-2020

Sl. No	Stn code	Monitoring Station	River	Regional Office	Apr-20		May-20		Jun-20		Jul-20		Aug-20		Sep-20		Oct-20		Nov-20		Dec-20		Jan-21		Feb-21		Mar-21	
					Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI
61	3566	KRS Dam Mandya	Cauvery	Mysuru	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
62	3567	D/s Shimsha near Madduar	Shimsha		*		*		*		*		*		C	S	C	S	C	S	C	S						
63	3568	Water supply intakepoint to Srirangapatna town	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
64	3569	Water supply intake point to Mandya town	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
65	3570	D/s of KR Nagar bridge	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
66	3571	U/s of KR Nagar	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
67	3572	Water supply intake point to Hunsur town	Lakshman Thirtha		*		*		*		*		*		C	S	C	S	C	S	C	S						
68	3573	D/s of Kushalanagar town	Cauvery		B	S	B	S	B	S	B	S	C	S	B	S	B	S	B	S	B	S						
69	3574	Water supply intake point to Madikeri town (Kootehole)	Cauvery		B	S	B	S	B	S	B	S	B	S	B	S	B	S	B	S	B	S						
70	3575	U/s Intake point to Nanjanagud & Gundlupet at Debur	Kabini		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
71	3576	Water supply intake point to Mysore pump house	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
72	3577	Water supply intake point to T. Narasipura	Kabini		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
73	3578	D/s of Cauvery Maddur water supply treatment plant @ Bachalli	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
74	3579	Water supply intake point at Kollegala, Dasanapura	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
75	3580	Water supply intake point to Malavalli	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
76	3581	Water supply intake point at Torekadanahalli	Cauvery		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
77	4087	NR Bridge, Ankola	Gangavali	Karwar	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
78	4088	Aghanashini River	Aghanashini		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
79	4089	Hadinabal Bridge	Gundabai		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
80	4090	NR Bridge, at Honnavara	Sharavathi		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						

Classification of Water Quality under National Water Quality Monitoring Programme from April - 2020 to December-2020

Sl. No	Stn code	Monitoring Station	Regional Office	Apr-20		May-20		Jun-20		Jul-20		Aug-20		Sep-20		Oct-20		Nov-20		Dec-20		Jan-21		Feb-21		Mar-21				
				Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	
26	3608	Varthur lake	Mahadevapura	E	US	D	US	D	US	D	US	D	US	E	US	E	US	E	US	E	US									
27	3610	Tubrahalli Lake		D	US	D	US	D	US	E	US	E	US	E	US	D	US	E	US	E	US	E	US							
28	3643	Beenniganahalli tank		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
29	4514	Sadramangala lake		D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US							
30	4515	Battarahalli Lake		D	US	D	US	E	US	E	US	D	US	D	US	E	US	E	US	D	US	D	US							
31	4516	Kundalahalli Lake		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
32	4517	Kowdhenahalli Lake		D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US							
33	4518	Garudacharpalya Lake		D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US							
34	4519	Rampura Lake		E	US		*	E	US	E	US	E	US	E	US	E	US	E	US	E	US	E	US							
35	4520	Chinnapanhalli Lake		D	US	E	US	E	US	E	US	D	US	E	US	E	US	D	US	D	US	D	US							
36	4521	Devarabeesanahalli Lake		D	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
37	4522	Vibhuthipura Lake		D	US	D	US	E	US		*		*		*		*		*		*		*							
38	4523	Nallurahalli Lake		E	US	E	US	E	US		*		*		*		*		*		*		*							
39	4524	Pattandur agarahara		D	US	E	US	E	US	D	US	D	US	D	US	E	US	D	US	D	US	D	US							
40	4525	Seetharam palya Lake		D	US	E	US	E	US	E	US	D	US	E	US	E	US	D	US	E	US	E	US							
41	4526	Dyavasandra Tank			*	D	US	E	US	E	US	E	US	D	US	D	US	E	US	D	US	D	US							
42	4527	Whitefield kere Lake			*		*		*		*		*		*		*		*		*		*							
43	4528	Doddakannehalli Lake			*		*		*		*		*		*		*		*		*		*							
44	4529	Kasavanahalli Lake		E	US	D	US	D	US	D	US	D	US		*	D	US	D	US	D	US	D	US							
45	3631	Nagarakere tank			*		*		*		*		*		*		*		*		*		*							
46	4530	Kammasandra Tank	E	US	E	US	E	US	E	US	D	US	E	US	D	US	E	US	E	US	E	US								
47	4531	Rayasandra Tank	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US								
48	4532	Chandapura Tank	E	US	E	US	D	US	D	US	D	US	D	US	D	US	E	US	E	US	E	US								
49	3590	Lalbagh tank	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US								
50	3591	Kempambudhi lake	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US								
51	3592	Yediyur lake	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US								
52	3638	Annaiappa Tank	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US								
53	4504	Sarakki Lake	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US								

Classification of Water Quality under National Water Quality Monitoring Programme from April - 2020 to December-2020

Sl. No	Stn code	Monitoring Station	Regional Office	Apr-20		May-20		Jun-20		Jul-20		Aug-20		Sep-20		Oct-20		Nov-20		Dec-20		Jan-21		Feb-21		Mar-21	
				Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI
54	1388	Ulsoor Lake Training Centre of Fish Breeding	BNG-City East	D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US						
55	3593	Ulsoor Lake near Temple		D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US						
56	3595	Byrasandra tank		E	US	E	US	E	US	E	US	E	US	D	US	D	US	D	US	D	US						
57	3594	Sankey Tank	BNG-City - West	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
58	2779	Hesaraghatta Reservoir	Dasarahalli	D	US	D	US	*		D	US	E	US	D	US	D	US	D	US	D	US						
59	3597	Hesaraghatta Tank		D	US	D	US	*		D	US	E	US	D	US	D	US	D	US	D	US						
60	3598	Herohalli Tank		D	US	D	US	D	US	E	US	E	US	E	US	D	US	D	US	D	US						
61	3599	Madavara Tank		D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US						
62	3606	Dasarahalli Tank		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
63	4094	Gangondana Halli Lake		E	US	E	US	E	US	E	US	E	US	D	US	D	US	D	US	E	US						
64	4095	Chikkabanvara Lake		E	US	E	US	D	US	E	US	E	US	D	US	D	US	D	US	E	US						
65	4096	Andhrhalli Lake		D	US	D	US	D	US	E	US	E	US	D	US	D	US	D	US	D	US						
66	4097	Kachohalli Lake		E	US	E	US	D	US	E	US	E	US	E	US	D	US	D	US	E	US						
67	4512	Viswaneedam Lake		E	US	E	US	E	US	E	US	E	US	D	US	D	US	D	US	E	US						
68	4538	Machohalli Lake		D	US	D	US	D	US	E	US	E	US	D	US	D	US	D	US	E	US						
69	4539	Doddabidarakallu Lake		E	US	E	US	E	US	D	US	E	US	D	US	D	US	D	US	E	US						
70	4540	Kammgondanahalli Lake		D	US	D	US	E	US	D	US	E	US	E	US	D	US	D	US	E	US						
71	4541	Alur Kere		*		*		*		*		*		D	US	E	US	D	US	D	US						
72	2778	T.G. Halli Reservoir		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
73	3596	Nayandanahalli Tank	*		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
74	3633	Subramanyapura Tank	D	US	D	US	D	US	D	US	D	US	E	US	*		*										
75	3634	Devarakere Tank	D	US	D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US							
76	3635	Malathahalli Tank	E	US	D	US	D	US	E	US	E	US	D	US	E	US	E	US	E	US							
77	3636	Bandematta Tank	E	US	E	US	D	US	D	US	D	US	D	US	*		*										
78	3639	Kengeri Tank	*		*		D	US	D	US	E	US	D	US	E	US	D	US	D	US							
79	3640	Uttarahalli Doraikere	D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US							
80	3641	Dhorekere	D	US	D	US	E	US	E	US	E	US	D	US	E	US	E	US	E	US							

Classification of Water Quality under National Water Quality Monitoring Programme from April - 2020 to December-2020

Sl. No	Stn code	Monitoring Station	Regional Office	Apr-20		May-20		Jun-20		Jul-20		Aug-20		Sep-20		Oct-20		Nov-20		Dec-20		Jan-21		Feb-21		Mar-21		
				Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class
81	4533	Ullal Lake	Rajarajeswarinagara	*		D	US	D	US	D	US	D	US	D	US	D	US	D	US	E	US							
82	4534	Sompura Lake		E	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
83	4535	Gubbalal kere		E	US	D	US	D	US	E	US	D	US	E	US	E	US	*		*								
84	4536	Hosakerehalli Lake		E	US	D	US	D	US	D	US	D	US	D	US	D	US	*			D	US						
85	4537	Chinnakurchi kere		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US					
86	3600	Shivapura tank	Peenya	E	US	D	US	D	US	E	US	E	US	D	US	D	US	E	US	E	US							
87	3601	Karihobanahalli lake		E	US	D	US	E	US	E	US	E	US	D	US	D	US	E	US	E	US							
88	3624	Puttnehalli Lake	Yelahanka	E	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
89	3625	Hebbal Lake		E	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US							
90	3626	Nagawara Tank		D	US	D	US	D	US	E	US	D	US	E	US	D	US	D	US	D	US							
91	3627	Jakkur Lake		D	US	D	US	E	US	E	US	E	US	E	US	D	US	D	US	E	US							
92	3628	Amruthahalli Lake		D	US	D	US	*		*		D	US	D	US	D	US	D	US	D	US							
93	3629	Allasandra Tank		D	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
94	3630	Yelahanka Tank		D	US	E	US	D	US	E	US	E	US	D	US	D	US	D	US	D	US							
95	4506	Abbigere Lake		D	US	D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US							
96	4507	Chelekere Lake		D	US	D	US	C	S	E	US	D	US	D	US	D	US	D	US	D	US							
97	4508	Singapura Lake		E	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US	E	US							
98	4509	Narasipura Lake		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
99	4510	Rachenahalli Lke		E	US	D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US							
100	4511	Kogilu kere		*		*		*		*		*		*		*		*		*								
101	3632	Veerapura Tank	Doddaballpura	D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US	E	US							
102	4503	Madhure Tank		D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US							
103	4505	Nelamangala Lake	Nelamangala	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
104	4513	Arashinakunte Kere		D	US	D	US	D	US	D	US	E	US	D	US	E	US	D	US	D	US							
105	3623	Anekal Doddakere Tank	Anekal	E	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							
106	3642	Jigani tank		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US							

Classification of Water Quality under National Water Quality Monitoring Programme from April - 2020 to December-2020

Sl. No	Stn code	Monitoring Station	Regional Office	Apr-20		May-20		Jun-20		Jul-20		Aug-20		Sep-20		Oct-20		Nov-20		Dec-20		Jan-21		Feb-21		Mar-21		
				Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class
133	3656	Nallikatte kere	Hassan	*		*		*		*		*		*		*		*		*								
134	3657	Kaachahalli koppalukere		E	US	E	US	E	US	E	US	E	US	E	US	E	US	E	US	E	US	E	US					
135	3658	Kallakatte kere		*		*		*		*		*		*		*		*		*		*						
136	3659	Mathana kere		E	US	E	US	E	US	E	US	E	US	D	US	D	US	D	US	E	US	E	US					
137	3660	Hunasina kere		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S					
138	3661	Kokkanaghattadodda kere		E	US	E	US	E	US	D	US	D	US	D	US	D	US	D	US	C	S	C	S					
139	3662	Kawshikakere		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S					
140	3663	Joladakatte		C	S	C	S	*		C	S	C	S	C	S	C	S	C	S	C	S	C	S					
141	3664	Basavanahallikere		*		*		*		*		*		C	S	C	S	C	S	C	S	C	S					
142	3665	Lingappanakatte		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S					
143	3666	Ganigarahosahallikere		*		*		*		*		*		C	S	C	S	C	S	C	S	C	S					
144	3667	Sathenahallidoddakere		C	S	C	S	*		*		*		E	US	D	US	D	US	D	US	D	US					
145	3668	Sodharahallikere		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S					
146	3669	Sheleramanahallikere		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S					
147	3670	Hainarakatte		*		*		*		*		*		C	S	C	S	C	S	C	S	C	S					
148	3671	Hanumanthapurakatte		*		*		*		*		*		C	S	C	S	C	S	C	S	C	S					
149	3672	Sankalapurakere		*		*		*		*		*		C	S	C	S	C	S	C	S	C	S					
150	3673	Havalikere		*		*		E	US	E	US	E	US	E	US	E	US	E	US	E	US	E	US					
151	3674	Sathamangalakere		C	S	C	S	*		C	S	C	S	C	S	C	S	C	S	C	S	C	S					
152	3675	B. Kalehallikere		*		*		*		*		*		C	S	C	S	C	S	C	S	C	S					
153	3676	Thavenahallikere	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
154	3677	Sharanabasveshwara kere	Kalaburagi	E	US	E	US	E	US	E	US	E	US	D	US	*	*	D	US	D	US	D	US					
155	3678	Ninjampura tank	Bidar	*		*		*		*		*		*		*		*		*		*						
156	3679	Bhutanala lake	Vijayapura	C	S	D	US	E	US	D	US	D	US	C	S	C	S	D	US	D	US	D	US					
157	3680	Killa lake	Belgavi	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S					
158	3681	Angol MI tank		E	US	D	US	D	US	D	US	E	US	E	US	D	US	D	US	D	US	D	US					
159	3682	Kakati pond		D	US	E	US	E	US	E	US	E	US	C	S	E	US	E	US	D	US	D	US					

Classification of Water Quality under National Water Quality Monitoring Programme from April - 2020 to December-2020

Sl. No	Stn code	Monitoring Station	Regional Office	Apr-20		May-20		Jun-20		Jul-20		Aug-20		Sep-20		Oct-20		Nov-20		Dec-20		Jan-21		Feb-21		Mar-21	
				Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI	Class	WQI
160	3683	Herekere	Dharwad	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
161	3684	Kelegere		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
162	3685	Navalooru lake		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
163	3686	Nirasagarakere		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
164	3687	Nuggikere		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
165	3688	Sadanakere		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
166	3689	Someshwarakere		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
167	3690	Unakalkere		D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
168	3691	Vimanabhuthikere	Davangere	C	S	C	S	C	S	C	S	C	S	C	S	B	S	C	S	C	S						
169	3692	Kunduvadakere		C	S	C	S	C	S	C	S	C	S	C	S	B	S	C	S	C	S						
170	3693	Bhathikere		D	US	D	US	D	US	E	US	D	US	D	US	D	US	D	US	D	US						
171	3694	Shanthisagarkere		C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
172	3695	Kondajjikere		D	US	D	US	C	S	C	S	C	S	C	S	C	S	C	S	C	S						
173	3696	Aianakere		E	US	E	US	E	US	E	US	E	US	E	US	E	US	E	US	E	US						
174	3697	Mattadakere	Chitradurga	E	US	E	US	D	US	D	US	D	US	D	US	D	US	D	US	D	US						
175	3565	Pilikula tank	Mangaluru	B	S	B	S	B	S	B	S	B	S	C	S	C	S	C	S	C	S						

Note: * – No Water in the River/ Reservoir/ Lake/Tank/Samples were not Collected.

NI-Newly Identified during April-2019

Class “A” – Drinking water source without conventional treatment but after disinfection.

Class “B” – Out door bathing (organized)

Class “C” – Drinking Water Source with conventional treatment followed by disinfection.

Class “D” – Propagation of wild life, fisheries

Class “E” – Irrigation, Industrial cooling, Controlled Waste disposal

WQI = Water Quality Index, S means Satisfactory, US means Unsatisfactory

WQI - Water Quality Index : (DO ≥ 4 mg/L BOD ≤ 3 mg/L FC ≤ 2500 MPN/100 ml & TC ≤ 5000 MPN/100 ml).